


sketch below shows a existing slab floor to a factory
the expansion material has deteriorated over time and in need of
replacing.

It was suggested that in replacing the expansion material Kordon TB
could be installed to assist the pervention of concealed termite entry



 **KORDON TERMITE BARRIER**

Subject

Sheet No.

renovation - detail 1

kd 045